



Pump no. 10-24290-1/2-3
 * 1 Service kit 09-45872
 A 1 Carrier complete - Medbringare komplett 09-45934

Pump No.	Pumptype	Cam Thickness	No. Mr.	Washer Bricks	No. Antal	No. Nr.
10-24290-1	F4B-9	1/1	3.3	01-45872	1	05-01-120
10-24290-2	F4B-903	1/3	4.0	01-45872	1	
10-24290-3	F4B-902	1/2	2.3	01-45872	2	

Part No.	Description	Material	Quantity
13	2 Kullager - Ball bearing		05-08-130
12	1 Applåring - Linseal		05-79-513
11	1 Bricka - Washer		05-01-120
10	1 Skruv - Screw		05-04-124
9	1 Skruv - Screw		05-04-163
8	1 Medbringare - Carrier		01-32260
7	1 Bricka - Washer		01-45659
6	1 Packning - Gasket		01-45284
5	1 Impeller		08-8108
4	1 Lock - Endcover		01-45282
3	1 Kam - Cam		See table
2	1 Axel - Shaft		01-45658
1	1 Pumphus - Body		01-74213

102-45934 09-45872 111K
 860515 I.F.
 Date



JOHNSON PUMP

Engine cooling